

## Stan of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director

JOHN R. BAZA Division Director

## **Inspection Report** Minerals Regulatory Program Report Date: September 26, 2006

Supervisor

Permit number: S/053/007

Date: September 12, 2006

**Time:** 5:40 PM

Mine Name: Bloomington Hills

Operator Name: Standard Gypsum Products, Inc.

Scott Gubler

1414 Fact 3850 South

St. George, Utah 84790 Inspector(s): Doug Jensen Other Participants: None Mine Status: Inactive	Weather: Clear, Hot		
<b>Elements of Inspection</b>	Evaluated	Comment	Enforcement
<ol> <li>Permits, Revisions, Transfer, Bonds</li> <li>Public Safety (shafts, adits, trash, signs, highwalls)</li> <li>Protection of Drainages / Erosion Control</li> <li>Deleterious Material</li> <li>Roads (maintenance, surfacing, dust control, safety)</li> <li>Concurrent Reclamation</li> <li>Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)</li> <li>Water Impoundments</li> <li>Soils</li> <li>Revegetation</li> <li>Air Quality</li> <li>Other</li> </ol>			
Purpose of Inspection:			
Inspected the site while I was in the area.  Directions to Site:			
See previous inspection report.			
Inspection Summary:  The site remains unchanged; there is a little morarea below the site is being developed and access seems indicated that he is ready to reclaim the site but nothing between the site of the s	to change with	each visit. The	
Conclusions and Recommendations: I will continue monitor the site when I am in the	e area.		
Inspector's Signature Dong Jenses	D D	rate: <u>9/2</u>	16/06
dj:pb cc: Standard Gypsum Products, Inc.			

John Blake, SITLA ML 40876

 $O: \label{local:local:moss} O: \label{local:local:moss} Washington \label{local:local:local:moss} So 122006 in sp. docolor \label{local:local:local:local:moss} John \label{local:$